

WARNING

WARNING

1
EMERG

1
**ENG/
APU**

Engine Malfunction In Flight	
Engine High-Side Failure In Flight Engine High-Side Failure On Deck Engine Low-Side Failure Engine Torque or TGT Spiking/Fluctuations Compressor Stall Engine High-Speed Shaft Failure Load Demand System Failure	